

Methods of test for

Footwear and footwear materials

Part 1. Adhesives

Section 1.1 Resistance of adhesive joints to heat (creep test)

NOTE. It is recommended that this Section should be read in conjunction with BS 5131 : Part 0, published separately.

Méthodes d'essais des chaussures et matériaux pour chaussures
Partie 1. Colles
Section 1.1 Résistance à la chaleur des assemblages collés (essai de fluage)

Prüfung von Schuhwerk und Schuhwerkstoffen
Teil 1. Klebstoffe
Abschnitt 1.1 Wärmebeständigkeit von Klebverbindungen

Foreword

This Section of BS 5131 has been prepared by the Textiles and Clothing Standards Policy Committee. It supersedes BS 5131 : Subsection 1.1.1 : 1976, which is withdrawn.

Compliance with a British Standard does not of itself confer immunity from legal obligations.