

Methods of test for

Footwear and footwear materials

Part 2. Solings

Section 2.10 Heat shrinkage of cellular solings

NOTE. It is recommended that this Section should be read in conjunction with BS 5131 : Part 0, published separately.

Méthodes d'essai des chaussures et des matériaux pour chaussures
Partie 2. Semelles
Section 2.10 Retrait thermique des semelles cellulaires

Prüfung von Schuhwerk und Schuhwerkstoffen
Teil 2. Sohlen
Abschnitt 2.10 Wärmeschrumpfung von Zellsohlen

Foreword

This Section of BS 5131 has been prepared under the direction of the Textiles and Clothing Standards Policy Committee. It supersedes BS 5131 : Section 2.10 : 1980, which is withdrawn.

Compliance with a British Standard does not of itself confer immunity from legal obligations.