



INTERNATIONAL STANDARD ISO 5599-2:2001
TECHNICAL CORRIGENDUM 1

Published 2007-02-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Pneumatic fluid power — Five-port directional control valves —
Part 2:
Mounting interface surfaces with optional electrical connector

TECHNICAL CORRIGENDUM 1

Transmissions pneumatiques — Distributeurs à cinq orifices principaux —

Partie 2: Plans de pose avec connecteur électrique facultatif

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO 5599-2:2001 was prepared by Technical Committee ISO/TC 131, *Fluid power systems*, Subcommittee SC 5, *Control products and components*.

Page 1:

Delete the footnote reference “2)” from ISO 1101, the footnote reference “3)” from ISO 1302 and footnotes 2 and 3 at the bottom of the page.

Page 3, Table 1, first row after the header (Size 1E), column to the far right-hand side (Orifice area):

Replace the dimension “79” with “70”.

Page 7, Table 3, third column from the left-hand side (Size 1E), last row before the footnotes (Orifice area):

Replace the dimension “79” with “70”.